


FRESE A SVASARE IN ACCIAIO SUPER RAPIDO

Particolarmente indicate per lavorazioni di precisione su acciai e fusioni in acciaio, sia legati che non legati, e metalli non ferrosi che non s'impastano, Ø gambo 3 x 40 mm
Velocità di taglio 60-180 m/min

Forma	Misure	giri/min*	N° d'ordine	€/pezzo
	7 x 10	10.000	10-102*	
	7 x 10	10.000	10-105*	
	4 x 2,8	20.000	10-108*	
	8 x 5,5	10.000	10-112*	
	6 x 6	13.000	10-113*	
	2,3 x 4	40.000	10-116*	
	6 x 10,5	13.000	10-120*	
	Ø 3,2	27.000	10-125*	
	Ø 6	13.000	10-128*	
	Ø 8 x 2	10.000	10-131*	
	Ø 12 x 3	7.000	10-133*	
	Ø 8 x 2	10.000	10-135*	
	Ø 10 x 2,3	8.000	10-136*	
	Ø 6 x 1	13.000	10-139*	
	Ø 10 x 1	8.000	10-141*	



Assortimento frese a svasare in acciaio superrapido

* Contenuto: 15 pezzi

N° d'ordine	€/Assortimento
10-145	

* = numero di giri max. (basato su una lunghezza sporgente L0 di 10 mm)

